

This corner was not set in the original government survey. A Legal 11-1855 by D.B. Hosbrook per Lawrence Township Legal Survey Book pg. 6 labels E Q 36-17-4 "F" and gives distances to N & W. Portion of page was destroyed. It appears that no falling is given to the W Q of 31-17-5. Legal 7-1866 per Smith per Lawrence Township Legal Survey Book pg. 12 labels corner "G", calls it a stone on brick and gives a witness tree. Distance given to NW corner of Sec. 31. Legal 11-1880 by Fatout per Lawrence Township Legal Survey Book pg. 38 labels the corner "4" and notes "buckeye". Distance is given to the NW of Sec. 31. Schmidt's boundary survey of Fort 5-1930 indicates corner and shows distances to adjacent boundary corners. No desc. on marker. Schneider Eng. (Job#20134) 1980 indicates an Iron pin with a cap set at corner of Fort ...Quarter master map #6138-129. Distance and bearing are given to corners N & E. Certified survey of boundary for Fort per Schneider indicates teh E Q of 36-17-4 as "U.S. Corps.Monu" set. Distances given to boundary corners, (although) they do not match 1930 survey. Schneider called double corner with falling as 7' S of E Q 36-17-4...but ignored double corner info and only used E Q of 36-17-4. US Corps monu and the iron pin in concrete were found destroyed in 9-1982 by Wilcoxen. Harrison set 10-6-1982 using Schneiders coordinates and JDB#20134. Re-tied 8-1-90 by Wilcoxen. Re-tied 12010-99 by Kiste.

1.1	C7	5	2	1	n	A
	61	J	J	Ţ	U	4

REF.	DISTANCE	DESCRIPTION
1.	93.11′	Mag nail w/washer N 40" sycamore leaning S 36"up
2,	13.60′	Mag nail w/washer W 12" ash 36"up
3.	26.80′	Mag nail w/washer N wooden fence post 36"up
4.	1.5′	MCSD sign post
5.	23.03′	Mag nail w/washer E 10" sycamore 24"up